



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 24443040	Plate Category	: PRIVATE
Transaction Date	: 24 FEB 2021 12:09:26	Plate Number	: 006301 EA
Queue Number	: 300216	Import Doc. Ref.	:
Chassis Number	: JTB11WJA0W8006301	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 1998
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.01 - Rusty		الصدأ
05.02 - Paint		الصبغ
05.08 - Chassis (Frame)		الشاصية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسؤولة عن العيوب الخفية

Test Certificate

✓ PASS



Transfer Certificate : 64995045
Chassis No : JTB11WJAOW8006301
Vehicle Make : TOYOTA
Vehicle Model : LAND CRUISER
Vehicle Class : Light Vehicle
Body Type : STATION
Fuel : Benzene
Color : White
Drive Direction : --
Dimensions : (H x W x L) -- x -- x --
Current Odometer : 198916 Kms.
Origin : Japan
Model Year : 1998
Gear Type : --
Engine Size : 4700 CC
Engine No : 2UZ0034670
Horse Power : 386
Axes No : 2
Cylinders : 8
No Of Doors : 5
No Of Seats : 8
G. V. W. : 2800 Kgs.
Empty Weight : 2500 Kgs.


Certificate Number : 5-TAS-2021-13680884
Inspection Date : 25-02-2021
Certificate Print Date : 25-02-2021
Services : Registration Test
Vehicle Testing Partner : Tasjeel
Vehicle Testing Center : Tasjeel Emirates Auction
Total Time Taken : 14 min 28 sec
Appointment Ref Number : --
Start Time : 17:07
End Time : 17:22
Lane : 01
Token No. : 12
Attempt : 1
Prints No. : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)



Parameter Readings

Service brake imbalance on front axle 3 %
Service brake imbalance on rear axle 1 %
Parking brake imbalance between LHS and RHS 1 %
Vehicle on Petrol CO Reading 1.99 %
Vehicle on Petrol HC Reading 183 PPM VOL

Inspection Findings

Discrepancies

	Old Value	New Value	Verified
Doors and Locks Incorrect Number of doors (does not require doc)	5	4	
Seats Incorrect Number of Seats	8	7	

Inspection Remarks: REAR BOTH SIDE CHASSIS END REPAIRED & FULL CHASSIS PAINTED

Payment Details

Inspection Performed by 74791
Payment Method VTP Credit Account
Transaction Number 13680884
Service Fees AED 170 Collected on 25/02/2021
Parking Slot No --
Service Name Registration Test
Attempt 1
Received by Raul Canceran Galang

① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

