CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2861314
Transaction Date	20 Oct 2026, 11:26:51
Site Name	840 - Emirates Auctions
Transaction Number	28898474 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SALYB2RV7J*******
Specification	Imported
Make	Range Rover
Model	Velar
Model Year	2018
Color	White
Mileage	118513 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	VIN CHASSIS NUMBER REPAIRED,FRONT LEFT SIDE CHASSIS OUTER DENT SKIRT OPEN	الشاسيه
02.B Chassis Number	VIN NUMBER REPAIRED REQUIRED CONFERMATION LETTER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	TRANSMISSION FUALT, NOT WORKING ,REFITTED, OIL WET GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE LENS FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Other	SUSPENSION REFITTED	اخري
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK	المكيف
08.B Roof Ceiling	LOOSE	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae