CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934064
Transaction Date	04 Nov 2026, 14:28:31
Site Name	840 - Emirates Auctions
Transaction Number	10394121 (CC10026) (CC10026)



Vehicle Details

Chassis Number	MDHAK3CR9C*******
Specification	GCC Specification
Make	Nissan
Model	Micra
Model Year	2012
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATHES , PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR THICK RUST PROOFED , PORTION DENT	الارضية
01.F Bumper	MISALIGN, PORTION DAMAGE FIX BY SCREW	دعامية
01.G Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		**الشاصي**
02.A Chassis	OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Other	ENGINE DRAIN PLUG DAMAGE FIXS BY SILICON	اخري
03.B Engine Visual Condition	ENGINE NOT START , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECK , PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHT NOT CHECK , LEFT SIDE BRACKET DAMAGE FIX BY WIRE	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION DAMAGE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	COOLANT LEVEL LOW	خزان التبريد
11 Battery Condition		حالة البطارية
11.A Battery Condition	MISSING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.