

Queue Number	2874487	Transaction Date	16 Oct 2026, 12:27:27
Site Name	840 - Emirates Auctions	Transaction Number	78871978 (CC10008) (CC10019)



Vehicle Details

Chassis Number	JN8AY2NY9J*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2018
Color	Black
Mileage	115331 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		
01.A Fenders	FRONT RIGHT SIDE PORTION REPAINTED,BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصيغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.F Sign of front accident	FENDER FRAME ,RADIATOR SUPPORT ,BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		
02.A Chassis	CHASSIS FRAME PORTION RUSTY	الشاسيه
02.B Chassis Number	VIN NUMBER REPUNCH ,RUSTY	رقم القاعدة
03 Engine Condition		
03.A Engine Visual Condition	OPEN,REFITTED	الحالة النظرية للمحرك
04 Seats Condition		
04.A Seat Condition	FRONT LOOSE ,COVER PORTION CRACKED & REAR RIGHT SIDE SEAT ADJUSTMENT NOT WORKING	حالة المقاعد
05 Exhaust System		
05.A Catalytic Converter	RIGHT SIDE COVER REWELDED	نظام العادم دبة البيئة

Condition	Remarks	الحالة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR OIL LEAK ,REFITTED	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
08.B Axle	BOOT CRACK	اكسلات
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	OK	المكيف
09.C Sun Visor	RIGHT SIDE PORTION DAMAGED	حاجب الشمس
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	GEAR LOCK COVER MISSING & KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae