CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2951324 |
| Transaction Date | 07 Nov 2026, 12:40:42 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 84507580 (CC10021) (CC10011) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | JTJJM7FX6P******* |
| Specification | GCC Specification |
| Make | Lexus |
| Model | GX 460 |
| Model Year | 2023 |
| Color | Silver |
| Mileage | 18731 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 8 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED | مدكار |
| 01.B Paint | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES | الصبغ |
| 01.C Doors | FRONT RIGHT SIDE PORTION REPAINTED | أبواب |
| 01.D Bumper | MISALIGN MINOR SCRATCHES | دعامية |
| 01.E Bonnet | REPLACED | غطاء المحرك |
| 01.F Sign of front accident | BUMPER FRAME,FENDER FRAME RADIATOR FRAME SUPPORT REPAIRED | وجود مؤشر لحادث في المقدمة |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | CHASSIS FRAME THICK RUSTY PROOFED,NOT VISIBLE,CHECKED VISIBLE AREA ONLY / OK | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | OK | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | الجير |
| 04.A Gear Box Visual Condition | OK | الحالة النظريه للجير |
| 04.B Road Test | NOT CHECK | فحص علي الطريق |
| **05 Tires and Rims Condition** | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2023 | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2023 DRY CRACK | الاطار الخلفي |

| Condition | Remarks | الحالة |
|---|---|---|
| **06 Interior Condition** | | **الحاله الداخليه** |
| 06.A Other | INTERIOR PARTS MINOR GETTING RUSTY | **اخري** |
| 06.B Mirror | CENTER VIEW MIRROR MINOR LOOSE | **المرايا** |
| 06.C AC Condition | OK | **المكيف** |
| 06.D Dash Board | LEATHER REFITTED PORTION LOOSE | **لوحة القياده** |
| 06.E Roof Ceiling | PORTION WORN OUT | **بطانه السقف** |
| 06.F Gear Shifting Lever | KNOB GETTING WORN OUT | **ذراع نقل السرعات** |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

**يمكنك التحقق من صحة الشهادة عبر الرابط**
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**