



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	07 Aug 2022, 13:41:05
Transaction Number	91437531 (CC10006)	Queue Number	312309



Chassis Number	JMYXTGA2WBZ700529
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	ASX
Model Year	2011
Color	White
Mileage	92384 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.B Fenders	FRONT BOTH SIDE BLASTIC (PAINT NOT CHECK), LEFT SIDE REPAIRED	مدكار
01.C Bumper	MISALIGN PORTION CRACKED	دعامية
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
03 Interior Condition		الحاله الداخليه
03.A Sun Visor	RIGHT SIDE LOOSE & STAND DAMAGED	حاجب الشمس
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK & ABNORMAL NOISY	حالة المحرك النظري
04.B Other	ENGINE STARTING KEY BROKEN	اخرى
05 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
05.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
06 Seats Condition		المقاعد
06.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
07 Chassis Condition		الشاسي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.