



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>23 Jan 2023, 15:52:38</b>
Transaction Number	<b>57515995 (CC10010)</b>	Queue Number	<b>657668</b>



Chassis Number	<b>5N1AR2M70DC684819</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Pathfinder</b>
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Chassis Condition</b>		<b>الشاسي</b>
01.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
02.B Bumper	MISALIGN	دعامية
02.C Trunk	NOT OPEN,BUTTON DAMAGED	صندوق
02.D Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	NOT CHECK	المكيف
03.B Odometer reading	NOT CHECK	قراءة عداد المسافات
03.C Sun Visor	LEFT SIDE LOOSE,RIGHT SIDE MISSING	حاجب الشمس
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSH CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
<b>05 Engine Condition</b>		<b>المحرك</b>

DEFECT	REMARKS	
05.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING,OIL LEAK	حالة المحرك النظري
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	NOT CHECK,OIL LEAK	حالة الجير النظري
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Rear Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الامامي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.