



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>26 Jan 2022, 15:40:29</b> |
| Transaction Number | <b>95826555 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>JA3AV66V19U030799</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Mitsubishi</b>        |
| Model            |                          |
| Model Year       | <b>2009</b>              |
| Color            | <b>Maroon</b>            |
| Mileage          | <b>84793 Miles</b>       |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>4</b>                 |
| Specification    | <b>USA Imported</b>      |

| DEFECT                                  | REMARKS   |                            |
|---|---|----------------------------|
| <b>01 Lights</b>                        |   | <b>الاضاءة</b>             |
| 01.A Warning Light                      | WARNING LIGHT ON IN DISPLAY   | ضوء تحذير                  |
| <b>02 Interior Condition</b>            |   | <b>الحالة الداخليه</b>     |
| 02.A AC Condition                       | NOT WORKING   | المكيف                     |
| 02.B Steering Wheel and control buttons | WORN OUT & HORN NOT WORKING   | عجلة القيادة وازرار التحكم |
| 02.C Mirror                             | VIEW MIRROR MISSING   | المرايا                    |
| <b>03 Body</b>                          |   | <b>جسم المركبة</b>         |
| 03.A Fenders                            | FRONT BOTH SIDE FENDER REPAINTED,PORTION REPAIRED & REFITTED & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED | مدكار                      |
| 03.B Trunk                              | REPAINTED,REFITTED  | صندوق                      |
| 03.C Sign of back accident              |   | وجود مؤشر لحادث في الخلف   |
| 03.D Floor                              | BACK PANEL&RIGH SIDE QUATER PANEL REPAIRED  | الارضية                    |
| 03.E Bonnet                             | REPAINTED,REFITTED,FADED,MISALIGN   | غطاء المحرك                |
| 03.F Paint                              | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED                                | الصبغ                      |
| 03.G Doors                              | REAR LEFT SIDE DOOR REPAINTED   | أبواب                      |

| DEFECT                             | REMARKS  |                        |
|------------------------------------|--|------------------------|
| 03.H Pillars                       | RIGHT SIDE C/PILLAR ,QUATER PANEL REPAIRED                     | القوائم                |
| 03.I Bumper                        | REPAINTED  | دعامية                 |
| 03.J Rusty                         | UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR<br>GETTING RUSTY | صدأ                    |
| <b>04 Suspension System</b>        |  | <b>ممتص الصدمات</b>    |
| 04.A Other                         | STABILIZER LINK BOOT CUT                                       | اخرى                   |
| 04.B Ball Joint                    | BOOT CUT   | مفصل كروي              |
| 04.C Shock Absorber                | SHOCK MODIFIED   | ممتص الصدمات           |
| <b>05 Exhaust System</b>           |  | <b>نظام العادم</b>     |
| 05.A Other                         | EXHAUST REAR MAFLER MODIFIED                                   | اخرى                   |
| <b>06 Tires and Rims Condition</b> |  | <b>الاطارات</b>        |
| 06.A Rear Tyre                     | BOTH SIDE 2017 CRACKED & EXPIRED                               | الاطار الخلفي          |
| 06.B Rims Condition                | RIMS HAVE MINOR SCRATCHES & FRONT LEFT SIDE 1 NUT<br>MISSING   | حالة الجنوط            |
| 06.C Front Tyre                    | BOTH SIDE 2017 CRACKED & EXPIRED                               | الاطار الامامي         |
| <b>07 Wipers and Arms</b>          |  | <b>المساحات</b>        |
| 07.A Wiper Arm &Blade              | WORN OUT   | ازرع المساحات والشفرات |
| <b>08 Transmission Condition</b>   |  | <b>الجير</b>           |
| 08.A Gear Box Mount                | LOWER MOUNT BUSH CRACKED                                       | كرسي الجير             |
| 08.B Road Test                     | NOT CHECK  | فحص علي الطريق         |
| 08.C Visual Gear Box<br>Condition  | OK   | حالة الجير النظرى      |
| <b>09 Chassis Condition</b>        |  | <b>الشاسيه</b>         |
| 09.A Chassis                       | REAR RIGHT SIDE CHASSIS EXTENSION REPAIRED                     | الشاسيه                |
| <b>10 Engine Condition</b>         |  | <b>المحرك</b>          |
| 10.A Visual Engine Condition       | ABNORMAL NOISY   | حالة المحرك النظرى     |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



✓ PASS

|                            |                   |
|----------------------------|-------------------|
| Change possession :        | 66128174          |
| Chassis No :               | JA3AV66V19U030799 |
| Vehicle Make :             | MITSUBISHI        |
| Vehicle Model :            | LANCER EVOLUTION  |
| Vehicle Class :            | Light Vehicle     |
| Body Type :                | SALOON            |
| Fuel :                     | Benzene           |
| Color :                    | Marone            |
| Drive Direction :          | Left Hand Side    |
| Dimensions : (H x W x L) : | -- x -- x --      |
| Current Odometer :         | 136459 Kms.       |
| Origin :                   | Japan             |
| Model Year :               | 2009              |
| Gear Type :                | Automatic         |
| Engine Size :              | 2000 CC           |
| Engine No :                | NIL               |
| Horse Power :              | --                |
| Axles No :                 | 2                 |
| Cylinders :                | 4                 |
| No Of Doors :              | 4                 |
| No Of Seats :              | 5                 |
| G. V. W. :                 | 1600 Kgs.         |
| Empty Weight :             | 1242 Kgs.         |

|                           |                     |
|---------------------------|---------------------|
| Certificate Number :      | 5-SHA-2022-15965092 |
| Inspection Date :         | 23-01-2022          |
| Certificate Print Date :  | 23-01-2022          |
| Services :                | Registration Test   |
| Vehicle Testing Partner : | Shamil              |
| Vehicle Testing Center :  | Shamil Muhaisnah    |
| Total Time Taken :        | 8 min 56 sec        |
| Appointment Ref Number :  | --                  |
| Start Time :              | 15:29               |
| End Time :                | 15:38               |
| Lane :                    | 02                  |
| Token No. :               | 281                 |
| Attempt :                 | 1                   |
| Prints No. :              | 1                   |

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

|                   |                        |                    |                           |
|-------------------|------------------------|--------------------|---------------------------|
|                   |                        |                    |                           |
| 19 KM             | 2 L                    | 4 AED              | 0.1 ton                   |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

## Parameter Readings

|   |   |   |  |
|---|---|---|--|
| Service brake imbalance on front axle<br>11 % | Service brake imbalance on rear axle<br>3 % | Parking brake imbalance between LHS and RHS<br>38 % | Vehicle on Petrol CO Reading<br>0.01 % |
| Vehicle on Petrol HC Reading<br>8 PPM VOL     |   |   |  |

## Inspection Remarks:

UNDER FLOOR & SUSPENSION PARTS MINOR RUST, REAR BOTH SIDE EXTENSION, BACK PANEL, QUARTER PANEL REPAIRED. BONNET COLOR MINOR FADED. EXHAUST MINOR MODIFIED

## Payment Details

|   |                                   |                                |   |
|---|-----------------------------------|--------------------------------|---|
| Inspection Performed by<br>74709 17766<br>17766 | Payment Method<br>Cash            | Transaction Number<br>15965092 | Service Fees<br>AED 170 Collected on 23/01/2022 |
| Parking Slot No<br>--                           | Service Name<br>Registration Test | Attempt<br>1                   | Received by<br>Wael Mohamed Mohamed Saleh       |

- ① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.  
② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصراً في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

