



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **16 May 2023, 12:55:33**
 Transaction Number **77150190 (CC10006)** Queue Number **716311**



Chassis Number **1HGCP2639CA612008**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Honda**
 Model **Accord**
 Model Year **2012**
 Color **Black**
 Mileage **001 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Arms	LOWER ARM BUSHES CUT	ازرع
01.B Ball Joint	BOOT CUT	مفصل كروي
02 Body		جسم المركبة
02.A Sign of side accident		وجود مؤشر لحادث في الجانب
02.B Paint	BODY PORTION REPAIRED ,PORTION REPAINTED,DENTS SCRATCHES,PORTION FADED..	الصبغ
02.C Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
02.D Bumper	MISALIGN,PORTION DAMAGE.	دعامية
02.E Floor	REAR RIGHT SIDE QUATER PANEL , BACK PANEL REPAIRED	الارضية
03 Transmission Condition		الجير
03.A Road Test	NOT CHECKED	فحص علي الطريق
03.B Visual Gear Box Condition	NOT CHECKED, REFITTED	حالة الجير النظري
03.C Gear Box Mount	BUSH CRACKED	كرسي الجير
04 Lights		الاضاءة
04.A Head Light	LENS FADED,ALL LIGHTS NOT CHCKED.	الاضاءة الرئيسية

DEFECT	REMARKS	
04.B Tail Light	LEFT SIDE COVER CRACKED	الانارة
05 Chassis Condition		الشاسي
05.A Chassis	REAR RIGHT SIDE CHASSIS EXTENSION END REPAIRED	الشاسيه
06 Steering Condition		المقود
06.A Steering Box	OIL LEAK	جهاز المقود
06.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07 Interior Condition		الحاله الداخليه
07.A AC Condition	NOT CHECKED	المكيف
07.B Odometer reading	NOT CHECKED	قراءة عداد المسافات
07.C Roof Ceiling	PORTION LOOSE	بطانه السقف
07.D Mirror	CENTER MIRROR FADED	المرايا
08 Engine Condition		المحرك
08.A Visual Engine Condition	ENGINE NOT START,ALL SYSTEM NOT CHECKED ,KEY MISSING, REFITTED ,OIL LEAK	حالة المحرك النظري
08.B Mount	BUSHES CUT	كرسي
09 Tires and Rims Condition		الاطارات
09.A Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
09.B Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
10 Seats Condition		المقاعد
10.A Seat Condition	PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.