CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2898245
Transaction Date	24 Oct 2026, 11:35:27
Site Name	840 - Emirates Auctions
Transaction Number	75278860 (CC10009) (CC10012)



Vehicle Details

Chassis Number	3VV3B7AX9M*******
Specification	Imported
Make	Volkswagen
Model	Tiguan
Model Year	2021
Color	Grey
Mileage	78098 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COVERED MUDDY OILY DIRTY	الارضية
01.F Trunk	REPAINTED PORTION REPAIRED , MISALIGN	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEADREPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS OUTER SLIGHTLY BEND	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY,MINOR SHAKING	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	PARTS GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Fog light	NOT WORKING	كشاف الضباب
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Other	STEERING HARD TO TURN	اخري
10 Interior Condition		الحاله الداخليه
10.A Other	INNER PARTS EGTTING RUSTY	اخري
10.B AC Condition	OK	المكيف
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae