



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **02 Aug 2022, 16:40:54**
 Transaction Number **98397226 (CC10006)** Queue Number **312309**



Chassis Number **KMHDG41C6FU254452**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Hyundai**
 Model **Elantra**
 Model Year **2015**
 Color **White**
 Mileage **187724 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition الحاله الداخليه		
01.A Odometer reading	NOT CHECKED	قراءة عداد المسافات
01.B AC Condition	NOT CHECKED	المكيف
01.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02 Suspension System ممتص الصدمات		
02.A Arms	LOWER ARM BUSHES CRACKED	ازرع
02.B Ball Joint	BOOT CUT	مفصل كروي
02.C Other	STABLIZER LINK BOOT CUT	اخرى
03 Tires and Rims Condition الاطارات		
03.A Front Tyre	BOTH SIDE 2017 CRACKED PUNCHER	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2015 CRACKED & EXPIRED	الاطار الخلفي
04 Body جسم المركبة		
04.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
04.B Doors	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
04.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT	الصبغ

DEFECT	REMARKS	
	,SCRATCHES,PORTION GETTING RUSTY	
04.D Floor	LEFT SIDE RUNNING BOARD DENT,FLOOR FULLY MUDDY	الارضية
04.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
05 Engine Condition		المحرك
05.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK & MINOR OIL LEAK	حالة المحرك النظري
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Other	ALL LIGHTS NOT CHECK	اخرى
07 Transmission Condition		الجير
07.A Road Test	NOT CHECKED	فحص علي الطريق
07.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
07.C Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Chassis Condition		الشاسي
09.A Chassis	FRONT BOTH SIDE CHASSIS MUDDY & CHECKED VISIBLE AREA OK	الشاسيه
10 Seats Condition		المقاعد
10.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.