





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18674635	Plate Category	: PRIVATE
Transaction Date	: 05 DEC 2019 11:45:24	Plate Number	: 9721 EA
Queue Number	: 123545	Import Doc. Ref.	:
Chassis Number	: FZJ800039721	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 1993
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: OTHERS
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.01 - Steering Box Oil, Adjust, Change		زيت صندوق عجلة القيادة
02.06 - Steering Wheel Alignment		میزانية عجلة القيادة
02.16 - Engine Mounting	CRACK	كراسي المحرك
02.17 - Gear Box Mounting	CRACK	كراسي ناقل الحركة
03 Brake System		نظام الفرامل
03.05 - Brake Pedal		نواصة الفرامل
05 Body		الهيكل
05.01 - Rusty		الصدأ
05.04 - Fenders		المدكار
05.05 - Bumpers		الدعامية
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب
06 General Items		الاشياء العامة
06.08 - Interior Lights		الانوار الداخلية
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok		التصافي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted		أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.



Test Certificate

Site Number	:	840-TASJEEL EM AUCTION	Plate Code	:	0
Transaction Number	:	18674635	Plate Category	:	PRIVATE
Transaction Date	:	05 DEC 2019 11:45:24	Plate Number	:	9721 EA
Queue Number	:	123545	Import Doc. Ref.	:	
Chassis Number	:	FZJ800039721	Manufacturer/Model	:	TOYOTA/LAND CRUISER
Engine Number	:		Model Year	:	1993
Vehicle Class	:	LIGHT VEHICLE	Vehicle Color	:	OTHERS
Service / Indicator	:	DSC AUCTION			

Statement of Vehicle Condition