CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2933995
Transaction Date	02 Nov 2026, 14:28:43
Site Name	840 - Emirates Auctions
Transaction Number	40270082 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1C4HJXDN8M*******
Specification	Imported
Make	Jeep
Model	Wrangler
Model Year	2021
Color	Grey
Mileage	74037 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	LEEFT SIDE FRONT & REAR REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION TREPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES/	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED. REFITTED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT .	الارضية
01.F Bumper	FRONT BUMPER MOUNT SOME BOLT MISISING , LOOSE ,NOT TIGHT PROPERLY .	دعامية
01.G Bonnet	PORTION REPAINTED	غطاء المحرك
01.H Pillars	LEFT SIDE REPAIRED.	القوائم
01.I Trunk	PORTION REPAINTED	صندوق
01.J Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident	LEFT SIDE DOOR PILLARS ROCKER PANEL ,DOOR POST ,WHEEL ARCH ,RUNNING BOARD REPAIRED ,	وجود مؤشر لحادث في الجانب
02 Chassis Condition		**الشاصي**
02.A Chassis	LEFT SIDE CHASSIS OUTER SKIRT , BODY ,MOUNT SUSPENSION BRACKET REPAIRED DENT ,CHASSIS THICK RUSTPROOFED ,	الشاسيه
02.B Other	REMOVE RUSTRPOOF FROM CHASSIS FOR INSPECCTION .	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	COMPONENT PARTS GETTING RUSTY .MINOR SHAKING	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	COMPONENT PARTS GETTING RUSTY , MINOR JERKING.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED ..	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025.	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	SUSPENSION PARTS REFITTED .	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS RUSTY ,SIGN OF WATER FLOODED.	اخري
09.B AC Condition	OK	المكيف
09.C Door Panel	PORTION LOOSE ,REFITTED .	لوحة بطانة الباب
09.D Air Bag	OPEN REFITTED .	وسائد هوائية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae