CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2976862
Transaction Date	13 Nov 2026, 15:07:20
Site Name	840 - Emirates Auctions
Transaction Number	52350699 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WF0TD34L88*******
Specification	GCC Specification
Make	Ford
Model	Focus
Model Year	2008
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS AND SCRATCHES	الصبغ
01.C Doors	FRONT BOTH SIDE REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	NOT OPEN PROPERLY.	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED CHECKED ONLY VISIBLE AREA OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	NOT STARTING ALL SYSTEM NOT CHECKED REFITTED OIL LEAK PARTS MISSING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDES 2020 EXPIRED CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CRACKED	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECKED	المكيف
11.C Sun Visor	RIGHT SIDE MISSING	حاجب الشمس
11.D Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae