



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Jul 2022, 17:51:59
Transaction Number	97422084 (CC10006)	Queue Number	312309



Chassis Number	WBA3A5G58FNS82714
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	328
Model Year	2015
Color	Blue
Mileage	25053 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	LEFT SIDE BOTH REPAINTED	أبواب
01.B Bumper	FRONT LOOSE & MISALIGN	دعامية
01.C Paint	BODY PORTION REPAIRED,REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.D Bonnet	REPAINTED	غطاء المحرك
01.E Floor	FRONT FLOORING COVER DAMAGED	الارضية
01.F Other	REAR BOTH SIDE QUARTER PANEL REPAIRED, FRONT BULK HEAD,RADIATOR SUPPORT REFITTED	اخرى
01.G Windshield	FRONT WINDSHIELD CRACKED	زجاج
01.H Fenders	PORTION REPAIRED, REPAINTED & FRONT FENDER REFITTED	مدكار
02 Engine Condition		المحرك
02.A Smoke	WHITE SMOKE	دخان
02.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
03 Interior Condition		الحالة الداخلية
03.A AC Condition	OK	المكيف
03.B Door Panel	COVER PORTION DAMAGED	لوحة بطانة الباب

DEFECT	REMARKS	
03.C Power Window Switch	REAR LEFT SIDE NOT WORKING	مفتاح النافذه
04 Lights الاضاءة		
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04.B Fog light	LEFT SIDE MISSING	كشاف الضباب
05 Transmission Condition الجير		
05.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Steering Condition المقود		
06.A Steering Oil	MINOR OIL LEAK	زيت المقود
07 Suspension System ممتص الصدمات		
07.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
08 Chassis Condition الشاصي		
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
09 Tires and Rims Condition الاطارات		
09.A Front Tyre	BOTH SIDE 2017 EXPIRED , CRACKED & WORN OUT	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2017/2018 CRACKED & EXPIRED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.