

Queue Number 2873653

Transaction Date 16 Oct 2026, 16:14:58

Site Name
840 - Emirates AuctionsTransaction Number
14192290 (CC10009) (CC10012)

Vehicle Details

Chassis Number	2FMPK4J87J*****
Specification	Imported
Make	Ford
Model	Edge
Model Year	2018
Color	Grey
Mileage	165460 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	CENTER FLOOR COVERED ,FLOOR PORTION LEFT SIDE RUNNING	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Windshield	FRONT SPOT CRACK	زجاج
01.H Roof	REAR SKIRT MISSING	السقف
01.I Trunk	MISALIGN	صندوق
01.J Sign of side accident	FRONT LEFT SIDE RUNNING BOARD ROCKER PANEL WHEEL HOUSING REPAIRED,BEND & LEFT SIDE ROCKER PANEL DENT	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	-----------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظرية للجير
--------------------------------	------------------------------	----------------------

Condition	Remarks	الحالة
04.B Propeller Shaft	MISSING	ناقل الحركة
04.C Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	REAR BLADE MISSING	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE BRACKET DAMAGED , REPAIRED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE MINOR CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION GETTING RUSTY	اخرى
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	LEFT SIDE GLASS MODIFIED	المرآيا
09.C AC Condition	OK	المكيف
09.D Roof Ceiling	PORTION LOOSE	بطانه السقف
09.E Steering Wheel and control buttons	WORN OUT , HORN NOT WORKING	عجلة القيادة وازرار التحكم
09.F Sunroof	CURTAIN MISSING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae