CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877811
Transaction Date	19 Oct 2026, 12:12:41
Site Name	840 - Emirates Auctions
Transaction Number	10567584 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JN1EN61C84*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2004
Color	Red
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT .	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Pillars	BOTH SIDE PILLAR REPAIRED,	القوائم
01.F Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.G Sign of side accident	QUARTER PANEL WHEEL ARCH RUNNING BOARD REPAIRED DENT RUSTY HOLE WEAK.	وجود مؤشر لحادث في الجانب
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL ,SPARE WHEEL HOUSING REPAIRED,DENT .	وجود مؤشر لحادث في الخلف
01.I Vehicle Color	GOLDEN	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED DENT . REAR BOTH SIDE CHASISS EXTENSION COMPARTMENT FLOOR CROSS MEMBER CHANGED RUSTY .	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Gear Box Mount	BUSHES CUT .	كرسي الجير
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	EXPIRED CRACKED WORN OUT	الاطار الامامي
06.B Rear Tyre	EXPIRED CRACKED WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	CRACKED.	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
11.B Mirror	LOOSE FADED.	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Dash Board	PORTION DAMAGED	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.F Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**