

Queue Number 2862467

Transaction Date 14 Oct 2026, 12:13:10

Site Name
840 - Emirates AuctionsTransaction Number
69122535 (CC10008) (CC10025)

Vehicle Details

Chassis Number	VSKDD3C27J*****
Specification	GCC Specification
Make	Nissan
Model	Navara
Model Year	2018
Color	White
Mileage	271947 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING FADED , PORTION RUSTY	الصبغ
01.B Doors	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	PORTION RUSTY	الارضية
01.E Bumper	MISALIGN PORTION DAMAGED	دعامية
01.F Trunk	LEFT SIDE CABIN REPAINTED PORTION REPAIRED	صندوق
01.G Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY / OK	الشاسيه
02.B Chassis Number	VIN GETTING RUSTY	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY ,REFITTED ,ABNORMAL NOISY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS GETTING RUSTY ,REFITTED	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE LENS FADED	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	LEFT SIDE NOT WORKING	كشف الضباب
07.E Revers Light	ALYWAS ON	نور الرجوع للخلف
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	BUSHES CRACK	ازرع
09.B Arms	BUSHES CRACK	
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
10.B AC Condition	NOT COOLING , REAR GRILL PORTION DAMAGED	المكيف
10.C Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

