

Queue Number 2823352

Transaction Date 02 Oct 2026, 12:23:27

Site Name
840 - Emirates AuctionsTransaction Number
10001606 (CC10013) (CC10011)

Vehicle Details

Chassis Number 1B3AC46KX8*****
 Specification GCC Specification
 Make Dodge
 Model Avenger
 Model Year 2008
 Color Unknown
 Mileage 256327 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED, PAINT THICKNESS HIGH, DENTS SCRATCHES	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED / REINFORCEMENT DENT	الارضية
01.F Bumper	MISALIGN , DAMAGE , TOW HOOK COVER MISSING , FRONT GRILL DAMAGE	دعامية
01.G Windshield	FRONT BOTH SIDE OUTER PANEL CRACK GETTING FADED	زجاج
01.H Bonnet	REFITTED , MISALIGN	غطاء المحرك
01.I Pillars	RIGHT SIDE C PILLAR OUTER PANEL REPAIRED	القوائم
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
01.K Vehicle Color	ORANGE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION RUST PROOFED / CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Other	INTAKE BOX LOCK DAMAGED	اخرى
03.B Engine Visual Condition	MINOR OIL LEAK , OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Transmission Condition		الاجير
04.A Gear Box Visual Condition	MINOR JERKING , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظره للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	LEFT SIDE 2024 RIGHT SIDE 2025 CRACK WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE DAMAGE	الضوء الخلفي
06.C Indicator & Hazard light	LEFT SIDE LOW BEAM NOT WORKING	الاشارات
06.D Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B Mirror	CENTER MIRROR GETTING FADED	المرايا
08.C AC Condition	OK , CONTROL SWICTH PORTION LOOSE	المكيف
08.D Roof Light	FRONT LEFT SIDE & REAR BOTH SIDE LIGHT NOT WORKING	أنارة السقف
08.E Power Window Switch And Glass	MAIN SWITCH BUTTON GETTING FADED	مفتاح النافذه و الزجاج
08.F Sun Visor	BOTH SIDE GLASS COVER LOOSE CASING CRACK , RIGHT SIDE BRACKET DAMAGE LIGHT NOT WORKING	حاجب الشمس
08.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.H Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.I Gear Shifting Lever	KNOB & CHROME PANEL WORN OUT & PANEL PORTION CRACK	ذراع نقل السرعات
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	BOTTLE MODIFIED / FIX BY TIE CLIP	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae