

Queue Number 2853280

Transaction Date 10 Oct 2026, 12:46:18

Site Name
840 - Emirates AuctionsTransaction Number
45392654 (CC10013) (CC10011)

Vehicle Details

Chassis Number	KL1ZA5CA1H*****
Specification	GCC Specification
Make	Chevrolet
Model	Malibu
Model Year	2017
Color	Black
Mileage	214827 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED,RIGHT REPAIRED REPAINTED,BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING FADED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED PORTION DENT	الارضية
01.E Bumper	MISALIGN,MINOR DENTS SCRATCHES	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.G Trunk	REAR SWITCH MELTED	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS BULK HEAD END REPAIRED	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------	-----------------------

04 Seats Condition المقاعد

04.A Seat Belt	FRONT RIGHT SIDE STUCK	حزام الأمان
----------------	------------------------	-------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR JEKRING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	CENTER VIEW MIRROR GETTING FADED	المرآيا
09.C AC Condition	OK,GRILL PORTION FADED	المكيف
09.D Dash Board	FABRIC PORTION LOOSE	لوحة القيادة
09.E Engine Start Button	REMOTE WORN OUT PORTION DAMAGED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae