CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877770
Transaction Date	28 Oct 2026, 15:01:07
Site Name	840 - Emirates Auctions
Transaction Number	22207460 (CC10010) (CC10011)



Vehicle Details

Chassis Number	ZAR9320000*******
Specification	Imported
Make	Alfa Romeo
Model	156
Model Year	2004
Color	Silver
Mileage	107396 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED,MINOR DENTS, SCRATCHES , PORTION GETTING RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACK WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2018 CRACK EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018 CRACK EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK.	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT.	ربلة المقود
09.B Steering Box	OIL LEAK.	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	CENTER GETTING FADED,RIGHT SIDE LOOSE	المرايا
10.C AC Condition	NOT CHECK	المكيف
10.D Power Window Switch And Glass	MAIN SWITCH PANEL MISALIGN	مفتاح النافذه و الزجاج
10.E Dash Board	PORTION DAMAGED,PART MISSING	لوحة القياده
10.F Roof Ceiling	PORTION LOOSE	بطانه السقف
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae