

TEST CERTIFICATE

Site Number Transaction Number **840-Emirates Auctions**

37043992 (CC10006)

Transaction Date

28 Jul 2022, 18:09:18

Oueue Number 312309

Chassis Number

MMBJNKA40CD051216

Engine Number

Vehicle Class

Heavy

Manufacturer

Mitsubishi

Model

Model Year

2012

Color

White

Mileage

001 Km

Fuel Type

Diesel

No. Of Cylinders

Specification

GCC Specification

DEFECT REMARKS

01 Engine Condition المحرك

01.A Visual Engine Condition ENGINE NOT START ALL SYSTEM NOT CHECK OIL LEAK

حالة المحرك النظرى

02 Transmission Condition

02.A Visual Gear Box **NOT CHECK & OIL LEAK** حالة الجير النظرى

الجير

03 Steering Condition

Condition

المقود

03.A Steering Oil OIL LEAK زيت المقود

04 Suspension System

ممتص الصدمات

04.A Ball Joint **BOOT CUT**

مفصل كروي

04.B Arms LOWER ARM BUSH CRACKED

ازرع

04.C Leaf Spring **BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY**

05 Chassis Condition

الشاصي الشاسيه

05.A Chassis **OK & GETTING RUSTY**

06 Interior Condition

الحاله الداخلية

NOT CHECK

قراءة عداد المسافات

06.B AC Condition

06.A Odometer reading

NOT CHECK

المكيف

| DEFECT | REMARKS | |
|-----------------------------|--|------------------|
| 07 Lights | | الاضاءة |
| 07.A Brake Light | LEFT SIDE MISSING | نور الفرامل |
| 07.B Other | ALL LIGHTS NOT CHECK | اخري |
| 07.C Head Light | LENS FADED & CRACKED | الاضاءة الرئيسية |
| O8 Body | | جسم المركبة |
| 08.A Paint | BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHES & PORTION FADED, RUSTY | الصبغ |
| 09 Tires and Rims Condition | | الاطارات |
| 09.A Front Tyre | BOTH SIDE 2018 CRACKED & WORN OUT | الاطار الامامي |
| 09.B Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.