

Queue Number	2861813	Transaction Date	12 Oct 2026, 16:47:52
Site Name	840 - Emirates Auctions	Transaction Number	51986562 (CC10013) (CC10011)



Vehicle Details

Chassis Number	SCBFE63W3C*****
Specification	GCC Specification
Make	Bentley
Model	Continental
Model Year	2012
Color	Black
Mileage	118947 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition	Remarks	الحالة
01 Body		
01.A Fenders	FRONT RIGHT SIDE, REAR LEFT REPAINTED PORTION REPAIRED SIGN OF REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT SCRATCHES, PORTION RUSTY	الصبغ
01.C Doors	LEFT SIDE PORTION REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER FLOOR USPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED / COVERED PORTION DAMAGED DIRTY MUDDY / FOR FULL INSPECTION MAKE SATEM WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	الارضية
01.F Bumper	MISALIGN, PORTION MINOR CRACK SCRATCHES	دعامية
01.G Bonnet	MISALIGN , SHOCK WEAK	غطاء المحرك
01.H Trunk	REFITTED	صندوق
01.I Door Handle & Lock	LEFT SIDE AUTO CLOSE NOT WORKING, RIGHT SIDE OUTER LOCK HANDLE CHROME STRIP LOOSE	مقابض الأبواب والأقفال
01.J Sign of front accident		وجود مؤشر لحادث في المقدمة
01.K Sign of back accident		وجود مؤشر لحادث في الخلف

02 Chassis Condition

02.A Chassis	CHASSIS COVERED MUDDY OILY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN LAMINATED / PORTION GETTING RUSTY / CHECK DOOR POST PLATE	رقم القاعدة

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Engine Visual Condition	MINOR OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	FRONT RIGHT SIDE GUIDE HOLDER AUTO NOT WORKING	حزام الأمان
04.B Seat Condition	FRONT LEFT SIDE COVER PORTION DAMAGED,BOTH SIDE SEAT ADJUSTMENT SWITCH PORTION DAMAGED WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Hand Brake	SWITCH WORN OUT	فرامل اليد
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Other	SUSPENSION PARTS REFITTED	اخرى
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود
09.B Steering Boot	BOOT CUT	ربلة المقود
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT	اخرى
10.B Mirror	LEFT SIDE AUTO FOLDING NOT WORKING	المرآيا
10.C AC Condition	LOW COOLING,ADJUSTMENT NOT WORKING PROPERLY	المكيف
10.D Audio	SCREEN FADED	صوتيات
10.E Roof Ceiling	PORTION LOOSE	بطانه السقف
10.F Odometer reading	CLUSTER PANEL DISPLAY PORTION FADED	قراءة عداد المسافات
10.G Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT,ADJUSTMENT NOT WORKING PROPERLY	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10.J Engine Start Button	GETTING WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae