CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2922689
Transaction Date	29 Oct 2026, 13:23:25
Site Name	840 - Emirates Auctions
Transaction Number	75851286 (CC10013) (CC10019)



Vehicle Details

Chassis Number	1FTPX04VX9*******
Specification	GCC Specification
Make	Ford
Model	F 150
Model Year	2009
Color	White
Mileage	256332 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES,PORTION RUSTY PORTION FADED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.D Roof	PORTION HOLE	السقف
01.E Bonnet	REFITTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME DIRTY MUDDY GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN CHECK DOOR POST STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION CRACKED & ADJUSTMENT NOT WORKING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , MINOR JERKING , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B DIFFERENTIAL	REAR OIL LEAK	الدفرنشل

Condition	Remarks	الحالة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Suspension System		**ممتص الصدمات**
07.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	
07.B Arms	ARM BUSHES DRY CRACK	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		**الحاله الداخليه**
08.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Roof Ceiling	PORTION LOOSE	بطانه السقف
08.D Sun Visor	BOTH SIDE BRACKET DAMAGED,REPAIRED	حاجب الشمس
08.E Door Panel	PORTION DAMAGED,LOOSE	لوحة بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae