

Queue Number

2899773

Transaction Date

24 Oct 2026, 11:33:53

Site Name

840 - Emirates Auctions

Transaction Number

11965693 (CC10010) (CC10010)



Vehicle Details

Chassis Number

WDBTJ41H87*****

Specification

GCC Specification

Make

Mercedes

Model

CLK 200

Model Year

2007

Color

Silver

Mileage

N/A Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Sign of side accident	QUARTER PANEL WHEEL ARCH DENT .	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
---------------------	---------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	EXPIRED CRACKED DAMAGED.	الاطار الامامي
06.B Rear Tyre	EXPIRED CRACKED DAMAGED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUST.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK.	جهاز المقود
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخرى
11.B Mirror	RIGHT SIDE COVER DAMAGED.	المرآيا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Dash Board	WORN OUT PORTION LOOSE	لوحة القيادة
11.E Roof Ceiling	PORTION LOOSE	بطانة السقف
11.F Sun Visor	WORN OUT PORTION LOOSE.	حاجب الشمس
11.G Odometer reading	NOT CHECKED.	قراءة عداد المسافات
11.H Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae