CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877843
Transaction Date	19 Oct 2026, 12:12:37
Site Name	840 - Emirates Auctions
Transaction Number	24391559 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KMHJM81D19*******
Specification	GCC Specification
Make	Hyundai
Model	Tucson
Model Year	2009
Color	Blue
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT .	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Windshield	REAR BROKEN	زجاج
01.F Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ALL ENGINE MAJOR PARTS MISSING NOT START ALL SYSTEM NOT CHECKED,REFITTED ,OIL LEAK PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT CHECKED .	المكيف
10.C Dash Board	PORTION LOOSE.	لوحة القياده
10.D Roof Ceiling	PORTION LOOSE.	بطانه السقف
10.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
10.F Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae