



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 08 Mar 2022, 13:00:05 |
| Transaction Number | 56384746 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | JN10WGY60Z0863573 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Patrol |
| Model Year | 1997 |
| Color | White |
| Mileage | 474467 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|---|---|----------------------------|
| 01 Interior Condition | | الحاله الداخليه |
| 01.A Steering Wheel and control buttons | HAVE EXTRA COVER | عجلة القيادة وازرار التحكم |
| 01.B Door Panel | LOOSE & PORTION DAMAGED | لوحة بطانة الباب |
| 01.C Power Window Switch | FRONT RIGHT & REAR BOTH SIDE NOT WORKING ON MAIN SWITCH | مفتاح النافذه |
| 01.D Dash Board | DAMAGED | لوحة القيادة |
| 01.E AC Condition | REAR NOT WORKING | المكيف |
| 01.F Roof Ceiling | MODIFIED | بطانه السقف |
| 02 Body | | جسم المركبة |
| 02.A Paint | BODY TOTALY REPAIRED,REPAINTED & MINOR DENTS, SCRATCHES | الصبغ |
| 02.B Pillars | DOOR PILLAR REPAIRED & GETTING RUSTY | القوائم |
| 02.C Floor | BOTH SIDE RUNNING BOARD ,FLOOR RUSTY HOLE | الارضية |
| 03 Seats Condition | | المقاعد |
| 03.A Seat Condition | SEATS HAVE EXTRA COVER,LOOSE & REAR MISSING | حالة المقاعد |
| 04 Tires and Rims Condition | | الاطارات |

| DEFECT | REMARKS | |
|----------------------------------|--|--------------------------|
| 04.A Rear Tyre | LEFT SIDE 2019 WORN OUT & RIGHT SIDE 2017 EXPIRED,WORN OUT | الاطار الخلفي |
| 04.B Spare Tire &Tools | SPARE TIRE MISSING | الاطار الاحتياطي و العدة |
| 04.C Front Tyre | BOTH SIDE 2018/2020 WORNOUT | الاطار الامامي |
| 05 Engine Condition | | المحرك |
| 05.A Visual Engine Condition | OIL LEAK & REFITTED,SHAKING | حالة المحرك النظري |
| 05.B Mount | BUSH CRACKED | كرسي |
| 06 Transmission Condition | | الجير |
| 06.A Visual Gear Box Condition | OIL LEAK & REFITTED | حالة الجير النظري |
| 06.B Road Test | NOT CHECK | فحص علي الطريق |
| 06.C DIFFERENTIAL | FRONT DIFFERENTIAL OIL LEAK | الدفرنشيل |
| 07 Chassis Condition | | الشاسي |
| 07.A Chassis | FRONT RIGHT SIDE CHASSIS BULDGE&REAR ARCH MINOR BULDGE | الشاسيه |
| 07.B Chassis Number | DOOR STICKER REFITTED | رقم القاعدة |
| 08 Exhaust System | | نظام العادم |
| 08.A Modification | MODIFIED | تعديلات |
| 09 Lights | | الاضاءة |
| 09.A Tail Light | REAR LENS MINOR CRACKED | الانارة |
| 10 Steering Condition | | المقود |
| 10.A Steering Oil | OIL LEAK | زيت المقود |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

| | | |
|-----------------------------------|-------------------|---------------------------------|
| Possession Certificate : | 66286246 | |
| Chassis No : | JN10WGY60Z0863573 | |
| Vehicle Make : | NISSAN | |
| Vehicle Model : | PATROL | |
| Vehicle Class : | Light Vehicle | |
| Body Type : | STATION | |
| Fuel : | Benzene | |
| Color : | White | |
| Drive Direction : | -- | |
| Dimensions : (H x W x L) : | -- x -- x -- | |
| Current Odometer : | 474468 Kms. | |
| Origin : | Japan | Model Year : 1997 |
| Gear Type : | Manual | Engine Size : 3500 CC |
| Engine No : | TB42131524 | Horse Power : -- |
| Axles No : | 2 | Cylinders : 6 |
| No Of Doors : | 4 | No Of Seats : 7 |
| G. V. W. : | 2300 Kgs. | |
| | | Empty Weight : 1947 Kgs. |

| | | |
|----------------------------------|---------------------|-------------------------|
| Certificate Number : | 5-TAS-2022-16801223 | |
| Inspection Date : | 19-05-2022 | |
| Certificate Print Date : | 19-05-2022 | |
| Services : | Registration Test | |
| Vehicle Testing Partner : | Tasjeel | |
| Vehicle Testing Center : | Tasjeel Al Aweer | |
| Total Time Taken : | 13 min 47 sec | |
| Appointment Ref Number : | -- | |
| Start Time : | 20:10 | End Time : 20:24 |
| Lane : | 03 | Token No. : 325 |
| Attempt : | 1 | Prints No : 1 |

Parameter Readings

| | | | |
|--|---|--|-------------------------------------|
| Service brake imbalance on front axle | Service brake imbalance on rear axle | Parking brake imbalance between LHS and RHS | Vehicle on Petrol CO Reading |
| 23 % | 15 % | 10 % | 4.34 % |
| Vehicle on Petrol HC Reading | | | |
| 741 PPM VOL | | | |

Inspection Findings

| Defects | Issue | Severity |
|---|--|----------|
| Fuel tank and pipings REPAIR FUEL LEAK FROM PIPE | Leaking | Major |
| Axles REPAIR ROMANA OIL LEAK | Others (Major) | Major |
| Vehicle Floor REPAIR RUNNING BOARD & QUARTER PANEL RUSTY HOLE | Others (Major) | Major |
| Spare Tire | Missing (Major) | Major |
| Tire | Date of manufactured tampered or expired | Major |
| CHANGE ALL TIRE WORN OUT & OLD | | |

Inspection Remarks: Bulk head,fender,fender frame,wheel housing repaired.

Payment Details

| | | | |
|--------------------------------|-----------------------|---------------------------|---------------------------------|
| Inspection Performed by | Payment Method | Transaction Number | Service Fees |
| 71051 | Cash | 16801223 | AED 170 Collected on 19/05/2022 |
| Parking Slot No | Service Name | Attempt | Received by |
| -- | Registration Test | 1 | Bajurdeen Abdul Gafoor |

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- 1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.