

Queue Number 2837754

Transaction Date 06 Oct 2026, 15:02:37

Site Name
840 - Emirates AuctionsTransaction Number
40073428 (CC10013) (CC10011)

Vehicle Details

Chassis Number WVWSV1AJ5E*****
 Specification GCC Specification
 Make Volkswagen
 Model Jetta
 Model Year 2014
 Color Grey
 Mileage 121720 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE ALIGN REPAIRED REFITTED,RIGHT REPAINTED & REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصيغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED MUDDY DIRTY	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Pillars	LEFT SIDE ROCKER PANEL COVER PORTION LOOSE	القوائم

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	MOUNT RUBBER CRACK	كرسي
03.B Engine Visual Condition	OIL PAN DENT , REFITTED , PARTS GETTING RUSTY , DRIVE BLTE NOISY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , OIL PAN DENT , PARTS GETTING RUSTY , INNER COMPARTMENT SHIFTING CABLE LINK BUSH MISSING CABLE LOOSE	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES,WHEEL HUB OUTER COVER & NUT MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE PORTION CRACKED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Brake Light	LEFT NOT WORKING	نور الفرامل
07.D Revers Light	NOT WORKING	نور الرجوع للخلف
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	REFITTED	ازرع
09.B Arms	ARM BUSHES MINOR DRY CRACK	
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY (SIGN OF FLOODED)	اخرى
10.B Mirror	ADJUSTMENT NOT WORKING SWITCH DAMAGED	المرايا
10.C AC Condition	NO COOLING,REAR GRILL PORTION LOOSE ADJUSTER MISSING	المكيف
10.D Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
10.E Roof Ceiling	REFITTED,PORION LOOSE	بطانه السقف
10.F Door Panel	PORION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Sunroof	NOT WORKING PROPERLY,NOISY	فتحت سقف
10.I Gear Shifting Lever	KNOB,DUST COVER,PANEL WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	SIGN OF WATER LEAK	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae