

Queue Number

2823316

Transaction Date

01 Oct 2026, 16:53:04

Site Name

840 - Emirates Auctions

Transaction Number

60765224 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WDB1714561*****
Specification	Imported
Make	Mercedes
Model	SLK350
Model Year	2007
Color	White
Mileage	119384 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	CONVERTIBLE SIDE COVER PORTION DAMAGED	السقف
01.H Bonnet	RIGHT SIDE GRILL PORTION DAMAGED	غطاء المحرك
01.I Trunk	MISALIGN	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONTLEFT SIDE CHASSIS END WITH BRACKET BEND	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED COMPONENT MISSING,SHAKING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED GETTING RUSTY, JERKING	الحالة النظرية للجير
--------------------------------	---------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	NOT WORKING	ضوء تحذير
06.B Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	NOT COOLING	المكيف
08.C Audio	NOT WORKING , LOOSE , PANEL CRACK	صوتيات
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	OIL WATER MIXED	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae