CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945061
Transaction Date	09 Nov 2026, 13:04:15
Site Name	840 - Emirates Auctions
Transaction Number	65757798 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MHFYX59G9E*******
Specification	GCC Specification
Make	Toyota
Model	Fortuner
Model Year	2014
Color	Black
Mileage	427750 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Doors	REAR LEFT SKIRT MISSING. FRONT LEFT DENT	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED .	غطاء المحرك
01.G Trunk	REFITTED INNER PANEL MISSING PORTION DAMAGED	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUSTY MUDDY PORTION DENT .	الشاسيه
02.B Chassis Number	VIN AREA GETING RUSTY.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DIRTY LOOSE PORTION DAMAGED .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED DAMAGED.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED DA,MAGED,	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	DAMAGED.	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	LENS FADED, ALL LIGHTS NOT CHECK	اخري
11.B Mirror	LOOSE PORTION FADED.	المرايا
11.C AC Condition	NOT CHECKED	المكيف
11.D Dash Board	PORTION LOOSE.	لوحة القياده
11.E Roof Ceiling	LOOSE DIRTY PORTION CUT .	بطانه السقف
11.F Sun Visor	LOOSE.	حاجب الشمس
11.G Door Panel	WORN OUT PORTION DAMAGED	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**