CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2907216 |
| Transaction Date | 26 Oct 2026, 16:51:04 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 64899196 (CC10013) (CC10019) |




## Vehicle Details

| | |
|---|---|
| Chassis Number | JTNBZ4HK0R******* |
| Specification | GCC Specification |
| Make | Toyota |
| Model | Camry |
| Model Year | 2024 |
| Color | Grey |
| Mileage | 128598 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 6 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | **جسم المركبة** |
| 01.A Paint | BODY PORTION REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES . | الصبغ |
| 01.B Doors | FRONT LEFT SIDE PORTION REPAINTED & FRONT RIGHT SIDE PORTION REPAINTED ,PORTION REPAIRED | أبواب |
| 01.C Rusty | UNDER FLOOR SUSPENSION PARTS GETTING RUSTY | صدأ |
| 01.D Floor | UNDER FLOOR COMPLETELY THICK RUST PROOFED | الارضية |
| 01.E Bumper | MISALIGN LIGHT COVER CRACK | دعامية |
| 01.F Bonnet | PORTION REPAINTED ,PORTION REPAIRED | غطاء المحرك |
| **02 Chassis Condition** | | **الشاصي** |
| 02.A Chassis | CHASSIS RUST PROOFED COVERED CHECK VISIBLE AREA ONLY / OK | الشاسيه |
| **03 Engine Condition** | | **المحرك** |
| 03.A Engine Visual Condition | MINOR OIL LEAK , PARTS GETTING RUSTY | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | **الجير** |
| 04.A Gear Box Visual Condition | MINOR OIL LEAK , PARTS GETTING RUSTY | الحالة النظريه للجير |
| 04.B Road Test | NOT CHECKED | فحص علي الطريق |
| **05 Tires and Rims Condition** | | **الاطارات** |
| 05.A Front Tyre | LEFT SIDE 2023 & RIGHT SIDE 2026 | الاطار الامامي |

| Condition | Remarks | الحالة |
|---|---|---|
| 05.B Rear Tyre | BOTH SIDE 2025 | الاطار الخلفي |
| 05.C Rims Condition | MINOR DENT SCRATCHES | حالة الجنوط |
| **06 Interior Condition** | | الحاله الداخليه |
| 06.A Other | INTERIOR PARTS GETTING RUSTY | اخري |
| 06.B Mirror | CENTER MIRROR PORTION LOOSE | المرايا |
| 06.C AC Condition | OK | المكيف |
| 06.D Gear Shifting Lever | KNOB WORN OUT | ذراع نقل السرعات |
| **07 Engine Cooling System** | | نظام تبريد المحرك |
| 07.A Coolant tank | WATER LEVEL LOW | خزان التبريد |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**