



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>10 May 2022, 17:22:59</b> |
| Transaction Number | <b>24435594 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>SALLSAAD4CA724012</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Range Rover</b>       |
| Model            | <b>Sport</b>             |
| Model Year       | <b>2012</b>              |
| Color            | <b>Silver</b>            |
| Mileage          | <b>102205 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>8</b>                 |
| Specification    | <b>GCC Specification</b> |

| DEFECT                             | REMARKS                                     |                        |
|------------------------------------|---|------------------------|
| <b>01 Body</b>                     |   | <b>جسم المركبة</b>     |
| 01.A Paint                         | BODY MINOR DENT ,SCRATCHES                  | الصبغ                  |
| 01.B Bonnet                        | SHOCK WEAK                                  | غطاء المحرك            |
| 01.C Trunk                         | REFITTED                                    | صندوق                  |
| <b>02 Interior Condition</b>       |   | <b>الحالة الداخليه</b> |
| 02.A Roof Ceiling                  | PORTION LOOSE                               | بطانه السقف            |
| 02.B Power Window Switch           | REAR LEFT SIDE NOT WORKING FROM MAIN SWITCH | مفتاح النافذه          |
| 02.C AC Condition                  | OK  | المكيف                 |
| <b>03 Transmission Condition</b>   |   | <b>الجير</b>           |
| 03.A Road Test                     | NOT CHECK                                   | فحص علي الطريق         |
| 03.B Visual Gear Box Condition     | MINOR OIL LEAK & REFITTED                   | حالة الجير النظري      |
| 03.C DIFFERENTIAL                  | MINOR OIL LEAK                              | الدفرنشيل              |
| <b>04 Tires and Rims Condition</b> |   | <b>الاطارات</b>        |
| 04.A Front Tyre                    | BOTH SIDE 2021                              | الاطار الامامي         |
| 04.B Rear Tyre                     | BOTH SIDE 2021                              | الاطار الخلفي          |

| DEFECT                       | REMARKS                     |                     |
|------------------------------|-----------------------------|---------------------|
| <b>05 Lights</b>             |                             | <b>الاضاءة</b>      |
| 05.A Warning Light           | WARNING LIGHT ON IN DISPLAY | ضوء تحذير           |
| 05.B Tail Light              | RIGHT SIDE CRACKED          | الانارة             |
| 05.C Fog light               | NOT WORKING                 | كشاف الضباب         |
| <b>06 Suspension System</b>  |                             | <b>ممتص الصدمات</b> |
| 06.A Arms                    | LOWER ARM BUSHES CRACKED    | ازرع                |
| <b>07 Engine Condition</b>   |                             | <b>المحرك</b>       |
| 07.A Visual Engine Condition | MINOR OIL LEAK & REFITTED   | حالة المحرك النظري  |
| <b>08 Chassis Condition</b>  |                             | <b>الشاسي</b>       |
| 08.A Chassis                 | OK                          | الشاسيه             |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.