



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Sep 2021, 10:49:20
Transaction Number	21558151 (CC10006)	Queue Number	312309



Chassis Number	5N1AA08C49N600774
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Armada
Model Year	2009
Color	Red
Mileage	0

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	مدكار
01.B Doors	REAR BOTH SIDE DOOR & TRUNK PORTION REPAIRED , REPAINTED	أبواب
01.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.D Bonnet	REPAINTED	غطاء المحرك
01.E Rusty	UNDER BODY PARTS, FLOORING GETTING RUSTY	صدأ
01.F Roof	PORTION REPAIRED & REPAINTED	السقف
01.G Windshield	FRONT CRACKED	زجاج
01.H Other	FRONT RIGHT SIDE DOOR NOT WORKING PROPERLY (OPEN/CLOSE)	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	OK	اخرى
03.B Mount	BUSHES CUT	كرسي
04 Seats Condition		المقاعد
04.A Other	OK	اخرى

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2015/2018 EXPIRED & CRACKED	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
08.C Indicator	FRONT LEFT SIDE NOT WORKING	الاشارات
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
11 Steering Condition		المقود
11.A Steering Boot	BOOT LEAKING	ربلة المقود
11.B Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
12 Interior Condition		الاجزاء الداخلية
12.A Other	OK	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.