



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 Sep 2021, 16:24:21
Transaction Number	17816943 (CC10006)	Queue Number	312309



Chassis Number	WDB46322717071498
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	G 300
Model Year	1992
Color	Grey
Mileage	125021

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, FLOORING , CHASSIS FRAME GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY RUST PROOFED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAIRED, REPAINTED & TOP GETTING RUSTY	السقف
01.H Bonnet	REPAIRED R& REPAINTED	غطاء المحرك
01.I Other	FOR RECHECK PROPERLY NEED TO ROMOVE RUST PROOFED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETELY THICK RUST PROOFED	الشاسيه
02.B Other	VIN NUMBER GETTING RUSTY & NOT VISABLE	اخرى
03 Engine Condition		المحرك
03.A Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى

DEFECT	REMARKS	
05 Exhaust System		نظام العادم
05.A Modification	NOISY	تعديلات
06 Transmission Condition		الجير
06.A Gear Box	OIL LEAK	الجير
06.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2016 CRACKED & EXPIRED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2016 CRACKED & EXPIRED	الاطار الخلفي
08 Wipers and Arms		المساحات
08.A Other	WORN OUT	اخرى
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية
09.B Other	OK	اخرى
10 Brake Condition		الفرامل
10.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
12 Steering Condition		المقود
12.A Steering Oil	ROMANO LEAKING	زيت المقود
12.B Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
13 Interior Condition		الاجزاء الداخلية
13.A Other	SLYDING ROOF NOT WORKING	اخرى
13.B Mirror	OK	المرابا
13.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details : 11 94529 Abu Dhabi Private

Chassis No : WDB46322717071498

Vehicle Make : MERCEDES

Vehicle Model : G63

Vehicle Class : Light Vehicle

Body Type : JEEP

Fuel : Benzene

Color : Gray

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 125021 Kms.

Origin : Germany

Model Year : 1992

Gear Type : --

Engine Size : 4700 CC

Engine No : NONE

Horse Power : 174

Axles No : 2

Cylinders : 6

No Of Doors : 2

No Of Seats : 5

G. V. W. :

3000 Kgs.

Empty Weight : 1900 Kgs.

Certificate Number : 1-TAS-2021-14992899

Inspection Date : 12-09-2021

Certificate Print Date : 12-09-2021

Services : Renewal Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Al Aweer

Total Time Taken :

2 min 2 sec

Appointment Ref Number : --

Start Time : 11:21

End Time : 11:23

Lane : 02

Token No. : 122

Attempt : 2

Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



3906 KM

Distance per
year



402 L

Fuel consumed
per year



652 AED

Fuel cost per
year



1.0 ton

Carbon footprint
per year

Inspection Findings

Discrepancies

Engine Size Discrepancy in Engine Size

Old Value

4700

New Value

3000

Verified

Inspection Remarks: MINOR ENGINE&STEERING BOX OIL LEAK// FLOOR THICK RUST PROOF

Payment Details

Inspection Performed by

62424

Payment Method

Cash

Transaction Number

14992899

Service Fees

AED 70 Collected on 12/09/2021

Parking Slot No

--

Service Name

Renewal Test

Attempt

2

Received by

Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

