CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2977922
Transaction Date	11 Nov 2026, 13:47:14
Site Name	840 - Emirates Auctions
Transaction Number	17967083 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WVWAP21F49*******
Specification	GCC Specification
Make	Volkswagen
Model	EOS
Model Year	2009
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED , DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , TOW HOOK COVER MISSING	دعامية
01.E Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.F Trunk	FIBER PAINT NOT CHECK	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START , ALL SYSTEM NOT CHECKED , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECK	المكيف
10.C Dash Board	PORTION WORN OUT	لوحة القياده
10.D Roof Ceiling	PORTION DAMAGE	بطانه السقف
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	WORN OUT	ذراع نقل السرعات
11 Battery Condition		حالة البطارية
11.A Battery Condition	MISSING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae