



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Jan 2023, 14:56:48
Transaction Number	12849370 (CC10010)	Queue Number	657827



Chassis Number	SJNBJ01B3CA471953
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Qashqai
Model Year	2012
Color	Black
Mileage	218412 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
01.B Head Light	LENS FADED,BRACKET DAMAGED	الاضاءة الرئيسية
02 Interior Condition		الحالة الداخليه
02.A AC Condition	LOW COOLING	المكيف
02.B Roof Ceiling	DAMAGED	بطانه السقف
02.C Mirror	REAR VIEW MIRROR FADED,RIGHT SIDE GLASS DAMAGED	المرايا
02.D Door Panel	PORTION DAMAGED	لوحة بطانة الباب
02.E Sunroof	CURTAIN DAMAGED	فتحت سقف
03 Body		جسم المركبة
03.A Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
03.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
03.C Bumper	MISALIGN,PORTION DAMAGED & FRONT BUMPER FRAME BEND	دعامية
03.D Sign of front accident		وجود مؤشر لحادث في المقدمة
03.E Other	FRONT FENDER FRAME, RADITOR SUPPORT, BULK HEAD REPAIRED	اخرى

DEFECT	REMARKS	
03.F Bonnet	REFITTED	غطاء المحرك
03.G Floor	PORTION DENT	الارضية
03.H Door Handle &Lock	REAR LEFT SIDE OUTER LOCK COVER MISSING	مقابض الأبواب والأقفال
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2022,MINOR CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2020 CRACKED ,	الاطار الخلفي
05 Engine Condition		المحرك
05.A Smoke	WHITE SMOKE	دخان
05.B Visual Engine Condition	OIL LEAK,REFITTED	حالة المحرك النظرى
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	REFITTED	حالة الجير النظرى
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSH CRACKED	ازرع
08 Chassis Condition		الشاسي
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.