

Queue Number 2453500

Transaction Date 16 Jun 2026, 15:19:12

Site Name
840 - Emirates AuctionsTransaction Number
63114502 (CC10009) (CC10011)

Vehicle Details

Chassis Number	2FMPK4J87H*****
Specification	GCC Specification
Make	Ford
Model	Edge
Model Year	2017
Color	Grey
Mileage	172846 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT,REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	FRONT RIGHT SIDE,REAR BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED,MUDDY CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY COVERED MUDDY , CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	FOR RECHECK PROPERLY REMOVE ALL UNDER COVERS	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED	الحالة النظرية للمحرك
------------------------------	-------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED, MINORJERKING	الحالة النظرية للجير
--------------------------------	------------------------------	----------------------

04.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	EXTRA STICKER	الاضاءة الرئيسية
06.B Tail Light	PORTION SIGN OF CRACK	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Hand Brake	SWITCH PORTION FADED	فرامل اليد
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	الزرع
09 Interior Condition		الحالة الداخلية
09.A Other	INNER PARTS GETTING RUSTY,	اخرى
09.B AC Condition	OK	المكيف
09.C Dash Board	PORTION LOOSE WORN OUT,LEATHER PORTION REFITTED	لوحة القيادة
09.D Roof Ceiling	REAR RIGHT SIDE HOLDER MISSING	بطانة السقف
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae