



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|-------------|
| Site Number | : 756-TASJEEL SHARJAH | Plate Code | : |
| Transaction Number | : 17528221 | Plate Category | : |
| Transaction Date | : 10 JUN 2019 10:39:23 | Plate Number | : |
| Queue Number | : 81396 | Import Doc. Ref. | : 60326 SHJ |
| Chassis Number | : WBA7E0104GG560326 | Manufacturer/Model | : BMW/730 |
| Engine Number | : | Model Year | : 2016 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | Mileage | : 101221 |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--------------------------------------------|--------|--------------------------------------------|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| 17 Shock Absorbers Test | | فحص مخمد الصدمات |
| 17.01 - Shock Absorber Test | Failed | فحص مخمد الصدمات |
| VISUAL TEST: | | |
| 02 Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 02.11 - Shock Absorbers | | مخمد الصدمات |
| | | FRT B/S SHOCK & RR LHS SHOCK ABSORBER WEAK |
| 05 Body | | الهيكل |
| 05.02 - Paint | | الصينغ |
| | | BODY PORTION MINOR SCRATCHES |
| 05.04 - Fenders | | المدكار |
| | | FRT FENDER REPD |
| 05.05 - Bumpers | | الدعامية |
| | | FRT BUMPER REPD |
| 05.07 - Floor | | الارضية |
| | | UNDER BODY FULLY COVERD |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | OK | الشاصي جيد |
| 09.09 - Engine And Gear Box Performance Ok | OK | فحص حالة الماكينة والجير |
| 09.25 - Body Repainted | | أثر صينغ في المركبة |
| | | FRT LHS FENDER PORTION RE-PAINTED |

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط