



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>20 Oct 2022, 17:44:36</b>
Transaction Number	<b>74090540 (CC10010)</b>	Queue Number	<b>609272</b>



Chassis Number	<b>JTMHX05J9H4144926</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Land Cruiser</b>
Model Year	<b>2017</b>
Color	<b>White</b>
Mileage	<b>82785 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b> <span style="float: right;">المحرك</span>		
01.A Visual Engine Condition	OK	حالة المحرك النظرى
<b>02 Transmission Condition</b> <span style="float: right;">الجير</span>		
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>03 Tires and Rims Condition</b> <span style="float: right;">الاطارات</span>		
03.A Front Tyre	BOTH SIDE 2021.	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
<b>04 Body</b> <span style="float: right;">جسم المركبة</span>		
04.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
04.B Rusty	UNDER SUSPENSION PARTS GETING RUSTY .	صدأ
04.C Bumper	REAR BUMPER MISALIGN,PORTION DAMAGE.	دعامية
04.D Trunk	PORTION REPAIRED,REPAINTED	صندوق
04.E Floor	RIGHT SIDE FOOT STEP SCRATCHES.	الارضية
<b>05 Interior Condition</b> <span style="float: right;">الحاله الداخليه</span>		

DEFECT	REMARKS	
05.A AC Condition	OK	المكيف
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Ball Joint	BOOT LEAK.	مفصل كروي
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	OK ,CHASSIS PORTION GETTING RUSTY .	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.