



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18058738	Plate Category	: PRIVATE
Transaction Date	: 12 SEP 2019 12:23:29	Plate Number	: 44664 EA
Queue Number	: 100131	Import Doc. Ref.	:
Chassis Number	: MMBJNKA508D044664	Manufacturer/Model	: MITSUBISHI/L200
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Failed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Failed	فحص الغاز العادم-الكربون
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.08 - Spare Tires	NONE	الاطار الاحتياطي
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing	INTERIOR COVER PARTLY TORN	المقاعد وحالتها وثبيتها
06.14 - Transmission Condition	OIL LEAK	حالة ناقل الحركة
07 Remarks		ملاحظات
07.04 - Others	478876 KM.	ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok		الشاصي جيد
09.10 - Engine Oil Leaking		تهريب زيت المحرك
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights	ENGINE LIGHT ON MISFIRE ROAD TEST NOT DONE	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted		أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.