

TEST CERTIFICATE

Site Number Transaction Number

01 Tires and Rims Condition

04.B Mount

05.A Paint

840-Emirates Auctions 92347959 (CC10006)

Transaction Date

16 May 2023, 14:11:38

Queue Number 716247

Chassis Number

KMHWG81R7FU693308

Engine Number

Vehicle Class Car

Manufacturer Hyundai

Model

H1

Model Year

2015

Color

White

Mileage

001 Km

Fuel Type

Petrol

No. Of Cylinders

Specification

GCC Specification

DEFECT **REMARKS**

02 Suspension System		ممتص الصدمات
01.B Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
01.A Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي

02.A Shock Ab	sorber OIL LEAK	ممتص الصدمات
02.B Ball Joint	BOOT CUT	مفصل كروي
02.C Arms	LOWER ARM BUSHE	S CUT

03 Interior Condition الحاله الداخليه

03.A AC Condition	NOT CHECKED	المكيف
03.B Odometer reading	NOT CHECKED	قراءة عداد المسافات

04 Engine Condition المحرك

04.A Visual Engine Condition	ENGINE NOT START,ALL SYSTEM NOT CHECKED ,KEY	حالة المحرك النظرى
	MISSING	

BUSHES CRACKED كرىسي

05 Body جسم المركبة

BODY MINOR DENT, SCRATCHES, PORTION RUSTY

الصبغ

الاطارات

DEFECT	REMARKS	
05.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
05.C Bumper	MISALIGN	دعامية
05.D Floor	UNDER FLOOR RUST PROOFED	الارضية
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى
06.B Gear Box Mount	BUSH CRACKED	كرسي الجير
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Chassis Condition		الشاصي
07.A Chassis	OK	الشاسيه
08 Seats Condition		المقاعد
08.A Seat Condition	REAR MISSING	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.