

Queue Number 2766920

Transaction Date 18 Sep 2026, 16:34:09

Site Name
840 - Emirates AuctionsTransaction Number
18718934 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SALKA9B78P*****
Specification	GCC Specification
Make	Range Rover
Model	HSE
Model Year	2023
Color	White
Mileage	81557 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.E Bumper	REAR REPAIRED , SKIRT MISSING	دعامية
01.F Roof	BACK SIDE REPAINTED	السقف
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	REFITTED , MISALIGN	صندوق
01.I Sign of side accident	REAR LEFT SIDE QUARTER PANEL REPAIRED INNER SHEET DAMAGED HOLE	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	OK	الشاسيه
--------------	----	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK	الحالة النظرية للمحرك
------------------------------	----------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	SIGN OF OIL WET	الحالة النظرية للجير
--------------------------------	-----------------	----------------------

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Lights		الاضاءة
06.A Tail Light	LEFT SIDE SCRATCHES	الضوء الخلفي
07 Steering Condition		المقود
07.A Steering Oil	SIGN OF OIL WET	زيت المقود
08 Interior Condition		الحالة الداخليه
08.A AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae