



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	05 Aug 2021, 06:35:43
Transaction Number	34637941 (CC1)	Queue Number	312309



Chassis Number	JN8FY1NYOGX012968
Engine Number	
Vehicle Class	STATION
Manufacturer	Nissan
Model	Patrol
Model Year	2015
Color	WHITE
Mileage	147573

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	PORTION REPAINTED & DENTS,SCRATCHES ON BODY	الصبغ
01.B Fenders	FRONT RIGHT SIDE PORTION REPAINTED	مدكار
01.C Rusty	UNDER BODY PARTS ,CHASSIS GETTIG RUSTY	صدأ
01.D Floor	FRONT RIGHT SIDE FENDER FRAME, BUMPER FRAME, BULK HEAD& CROSS MEMBER REPAIRED	الارضية
01.E Bonnet	REPAIRED& REPAINTED	غطاء المحرك
01.F Bumper	REFITTED & REPAINTED	دعامية
01.G Roof	SLIDING ROOF NOT WORKING POROPERLY	السقف
02 Chassis Condition		الشاصي
02.A Chassis Major	OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	MISSFIRING & REFITTED	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	FRONT 4WD DIFFRINTAL WELDED REPAIRED	الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2019	الاطار الامامي

DEFECT	REMARKS	
06.B Rear Tyre	BOTH SIDE 2018/2019	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WIPERS BLADE WORN OUT	اخرى
08 Suspension System		ممتص الصدمات
08.A Leaf Spring	FRONT LEFT SIDE CWIL SPRING MOUNT WELDED REPAIRED	
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Interior Condition		الاجزاء الداخلية
10.A AC Condition	OK	المكيف
10.B Other	ALL OK	اخرى
11 Steering Condition		المقود
11.A Other	ROMANO LEAKING	اخرى

The Test Certificate Shows the test Result at the time of inspection only.

Car Check is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
كار تشيك غير مسؤولة عن العيوب الخفية

