

Queue Number

2869237

Transaction Date

15 Oct 2026, 12:31:58

Site Name

840 - Emirates Auctions

Transaction Number

88838906 (CC10009) (CC10012)



Vehicle Details

Chassis Number

WP0ZZZ97ZC*****

Specification

GCC Specification

Make

Porsche

Model

Panamera

Model Year

2012

Color

Red

Mileage

210861 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.B Doors	REAR REFITTED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COVERED PORTION DENT	الارضية
01.E Bumper	MISALIGN , PORTION CRACK	دعامية
01.F Bonnet	REFITTED , HANDLE LOOSE , SHOCK WEAK NOT WORK	غطاء المحرك
01.G Trunk	REFITTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	CHECKED ONLY ON STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED SHAKING GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED , REAR CENTER CONSOLE BOX PORTION DAMAGED , FOLDING NOT WORKING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED, JERKING,SOMETIME NOT SHIFTTING PROPERLY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE PORTION CRACK	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
09 Suspension System		متنص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
09.B Other	SUSPENSION REFITTED	اخرى
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED	اخرى
10.B AC Condition	NOT COOLING , ADJUSTMENT BUTTON NOT WORKING	المكيف
10.C Power Window Switch And Glass	REAR SWITCH LOOSE	مفتاح النافذه و الزجاج
10.D Dash Board	LEATHER REPLACED , SIDE COVER PORTION DAMAGED	لوحة القيادة
10.E Roof Ceiling	PORTION LOOSE	بطانه السقف
10.F Door Panel	WORN OUT , REAR CIGARETTE COVER LOOSE	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT , HORN NOT WORK	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae