

Queue Number 2844381

Transaction Date 07 Oct 2026, 14:14:38

Site Name
840 - Emirates AuctionsTransaction Number
95452756 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WDDHF5EBXC*****
Specification	GCC Specification
Make	Mercedes
Model	E 300
Model Year	2012
Color	White
Mileage	147553 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	MINOR DENTS SCRATCHES ON BODY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED / COVER PORTION DAMAGED / REINFORCEMENT DENT	الارضية
01.D Bumper	MISALIGN,SCRATCHES	دعامية
01.E Bonnet	RELEASE HANDLE LOOSE,SHOCK WEAK	غطاء المحرك
01.F Other	RUNNING BOARD COVER PART MISSING	اخرى

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED DIRTY MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET , COMPONENTS REFITTED , MUDDY DIRTY , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION WORN OUT,BACK COVER PORTION LOOSE DAMAGED	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR JERKING , MUDDY , DIRTY , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 WORN OUT INNER CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	PORTION CRACK	الضوء الخلفي
07.B Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	الزرع
09 Steering Condition		المقود
09.A Steering Boot	BOOT CUT LEAK	ربلة المقود
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT LOCK HANDLE DAMAGED,CUP HOLDER SLIDING COVER DAMAGED	اخرى
10.B Mirror	LEFT SIDE COVER PORTION CRACKED	المرآيا
10.C AC Condition	OK,SWITCH PORTION DAMAGED	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING,SWITCH PORTION WORN OUT	مفتاح النافذه و الزجاج
10.E Audio	SCREEN PORTION FADED,SWITCH PORTION WORN OUT	صوتيات
10.F Roof Ceiling	PORTION LOOSE	بطانه السقف
10.G Sun Visor	LEFT SIDE MIRROR COVER LOOSE LIGHT NOT WORKING	حاجب الشمس
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Sunroof	CURTAIN NOT WORKING PROPERLY	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

