CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2915834
Transaction Date	27 Oct 2026, 16:44:28
Site Name	840 - Emirates Auctions
Transaction Number	70871654 (CC10013) (CC10019)

Vehicle Details

Chassis Number	WDDNG56X19*******
Specification	GCC Specification
Make	Mercedes
Model	S 350
Model Year	2009
Color	Black
Mileage	136190 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE,REAR RIGHT SIDE REPAINTED ,PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED / COVERED PORTION CRACK MINOR DENT	الارضية
01.F Bumper	MISALIGN / DISTRONIC RADAR MISSING	دعامية
01.G Bonnet	REPAINTED & GRILL PORTION DAMAGED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME BEND , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخري
03 Engine Condition		المحرك
03.A Other	DIPSTICK HOLDER DAMAGED	اخري
03.B Engine Visual Condition	OIL WET , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم
04.A Other	DENT	اخري

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	DELAY SHIFTING , JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
05.C DIFFERENTIAL	MOUNT RUBBER DRY CRACK	الدفرنشل
05.D Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2024 & RIGHT SIDE 2022	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP PORTION DAMAGED	اخري
08 Lights		الاضاءة
08.A Head Light	LENS FADED,RIGHT SIDE BRACKET DAMAGED.LOW BEAM NOT WORKING	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES SIGN OF MINOR DRY CRACK	ازرع
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT	ربلة المقود
10.B Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY & CENTER CONSOLE BOX LOCK DAMAGED	اخري
11.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
11.C AC Condition	OK	المكيف
11.D Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING PROPERLY,SWITCH LOOSE	مفتاح النافذه و الزجاج
11.E Audio	SCREEN FADED	صوتيات
11.F Dash Board	PORTION WORN OUT LOOSE	لوحة القياده
11.G Odometer reading	CLUSTER FADED	قراءة عداد المسافات
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Sunroof	GRILL MISSING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**