CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2940761
Transaction Date	03 Nov 2026, 16:59:52
Site Name	840 - Emirates Auctions
Transaction Number	34986101 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1N4AL3AP7J*******
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2018
Color	--
Mileage	217411 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED,PORTION REPAIRED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED MUDDY CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Vehicle Color	BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS END OUTER BRACKET REPAIRED INNER PORTION MINOR DENT,	الشاسيه
02.B Chassis Number	STICKER PORTION WORN OUT	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED SHAKING GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACKED DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY SIGN OF FLOODED & CENTER CONSOLE BOX COVER WORN OUT	اخري
08.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING & CENTER MIRROR PORTION LOOSE	المرايا
08.C AC Condition	NOT COOLING	المكيف
08.D Roof Ceiling	PORTION LOOSE	بطانه السقف
08.E Door Panel	PORTION LOOSE	لوحة بطانة الباب
08.F Air Bag	DAMAGED,MISSING	وسائد هوائية
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae