

Queue Number 2852518

Transaction Date 09 Oct 2026, 12:02:14

Site Name
840 - Emirates AuctionsTransaction Number
84355334 (CC10010) (CC10010)

Vehicle Details

Chassis Number	WDC1641861*****
Specification	GCC Specification
Make	Mercedes
Model	ML350
Model Year	2001
Color	Silver
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN SCRATCHES.	دعامية
01.G Vehicle Year Model	2006.	سنة صنع المركبة

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION CUT .	حالة المقاعد
---------------------	---------------	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES.,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS MINOR RUSTY.	اخرى
11.B AC Condition	NOT CHECKED .	المكيف
11.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.D Door Panel	PORTION WORN OUT .	لوحة بطانة الباب
11.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae