



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **18 Nov 2022, 10:03:45**
 Transaction Number **66658250 (CC10006)** Queue Number **625452**



Chassis Number **WAUZZZ4H5DN022857**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Audi**
 Model **A8**
 Model Year **2013**
 Color **Silver**
 Mileage **53893 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **Imported**

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	JERKING	حالة الجير النظري
02 Body		جسم المركبة
02.A Fenders	FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED,REFITTED	مدكار
02.B Bonnet	PORTION REPAIRED,REPAINTED & SHOCK WEAK & REFITTED	غطاء المحرك
02.C Doors	FRONT RIGHT SIDE PORTION REPAIRED REPAINTED	أبواب
02.D Bumper	FRONT ASSEMBLY REFITTED	دعامية
02.E Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
02.F Sign of front accident		وجود مؤشر لحادث في المقدمة
02.G Other	FRONT FENDER FRAME, RADITOR SUPPORT , BULK HEAD REPAIRED & BUMPER FRAME CRASH BOX DENT, BULT MISSING, LOWER SUPPORT CRACKED	اخرى
02.H Floor	UNDER BODY COVERD ONLY VISIBLE AREA CHECK	الارضية
03 Chassis Condition		الشاصي

DEFECT	REMARKS	
03.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
05 Interior Condition		الحاله الداخليه
05.A AC Condition	OK	المكيف
05.B Roof Ceiling	LOOSE	بطانه السقف
05.C Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
06 Engine Condition		المحرك
06.A Visual Engine Condition	OK	حالة المحرك النظري
06.B Smoke	WHITE SMOKE	دخان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.